TIRED OF GETTING CANNED?

"Oil canning" or the phenomenon depicted on the black trailer at the top is one of the most common occurences with aluminum cargo trailers.

This is caused by **temperature changes** as the aluminum expands and contracts over time and leads to this unsightly visual appearance.

To address this issue Piedmont Plastics® has developed **PolyCor™ AP**. PolyCor™ AP's unique structure enables a number of great benefits over aluminum siding.

POLYCOR™/ AP

- Prevents oil canning, even in the most extreme conditions
- Improved impact resistance
- Improved structural stability
- · Completely waterproof
- Reduces "road noise"



